



00238821

UIC

COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 175 API# 075 06361 0 INSPECTOR L. Robbins DATE 7/13/87

WELL NAME MT HOPE W-28

TYPE E

SITE INSPECTION X

FIELD 56150 MOUNT HOPE

WITNESS MIT _____

OPER 59100 MONAHAN* REX

LOCATION N4NE 30 9.0N 53.0W 6

MAX PERMITTED PRESS 1292 PSI DATE LAST INSPECTION 05/06/86 OUTCOME N
LAST REPORTED PRESS PSI 00/00 DATE LAST MIT 00/00/00
WELL RESTRICTIONS HOLE IN CSG - SI 4/1/86
REMEDIAL ACTION CSG LK - SI 4/1/86
COMPLETION TYPE TP

TUBING PRESSURE

ZONE DSND

MIT _____ INJECTING _____ PSI

MIT _____ NOT INJECTING SI PSITOP 4827
BOT 4838

P E R F S

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

MIT
PACKER
DEPTH _____CASING
SIZE 8 5/8
DEPTH 166SIZE 5 1/2
DEPTH 4980SIZE /
DEPTHSIZE /
DEPTH

PACKER 4735

LINER
TOP
SIZE /
DEPTHPBTVD 4980
TVDACCEPTABLE _____ NOT ACCEPTABLE X

REMARKS: Known CSG leak,
Flowline has been disconnected
from wellhead making it
inoperable. Tubing has been
pulled. Requires repair & mit
prior to reactivation.
J Robbins