

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2019

Submitted Date:

11/29/2019

Document Number:

679706377

FIELD INSPECTION FORM

Loc ID 316641 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74290
Name of Operator: RETAMCO OPERATING INC
Address: PO BOX 790
City: RED LODGE State: MT Zip: 59068

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Johnson, Joe	406-446-1568	joejohnson@retamco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290545	WELL	TA	12/01/2018	GW	103-11015	N. BARCUS CREEK 1-12	SI

General Comment:

[COGCC Inspection Report Summary.](#)

On 11-27-2019 at approximately 15:15, inspector Rick Moran, conducted a follow up inspection at Retamco Operating well North Barcus Creek 1-12 in Rio Blanco county of FIR document 679705213.

The following compliance issues are uncompleted:

- 1) Well head sign missing nearest public road & "911". Photo 2. Complete by 10-23-2019.
- 2) Barrel without label. Photo 3. Complete by 10-23-2019.
- 3) Barrel without secondary containment. Photo 3. Complete by 10-23-2019.
- 4) Broken deadman marker. Photo 4. Complete by 10-23-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706377.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign missing nearest public road and "911".		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/23/2019
Type	CONTAINERS		
Comment:	Barrel missing label.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/23/2019

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Deadman # & Marked	# 4		corrective date
Comment:	One broken deadman marker.		
Corrective Action:	Install proper guy line markers per Rule 1003.a.	Date:	10/23/2019
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 290545 Type: WELL API Number: 103-11015 Status: TA Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: No apparent significant soil migration, erosion, or soil movement on location.
Barrel is missing secondary containment.

Corrective Action: Repair or install berms or secondary containment devices per Rule 906.d.(1).

Date: 10/23/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402250615	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000732
679706378	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000730