

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402265679

Date Received:
12/17/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rowley, Darren

drowley@logosresourcesllc.com

Farrell, Larissa

lfarrell@logosresourcesllc.com

Sessions, Tamra

tsessions@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901023

Inspection Date: 10/24/2019

FIR Submit Date: 11/04/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325194

Location Name: BONDAD 33-10-N33N10W Number: 14NWSE County: LA PLATA

Qtrqr: NWSE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.101040 Longitude: -107.900790

FACILITY - API Number: 05-067-00 Facility ID: 214254

Facility Name: BONDAD 33-10 Number: 17

Qtrqr: NWSE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.101040 Longitude: -107.900790

CORRECTIVE ACTIONS:

1 CA# 133177

Corrective Action: Kochia debris needs to be removed and disposed of properly.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator Comment: Kochia debris was removed and disposed of on 11/15/2019. See attached pictures.

COGCC Decision: _____

COGCC
Representative:

2 CA# 133178

Corrective Action: Revegetation and stabilization measures are needed to stabilize erosion on the well pad cut-slope.

Date: 11/22/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator
Comment:

Re-seeding and stabilization measures have been installed to stabilize erosion on the well pad cut-slope.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed:

Title: Env/Reg Technician

Date: 12/17/2019 2:43:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402265701	Photo
402265703	Photo
402265704	Photos

Total Attach: 3 Files