

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402273986

Date Received:
12/30/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Alyssa Beard

(303) 244-8114

abeard@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404553

Inspection Date: 02/15/2019

FIR Submit Date: 02/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 317682

Location Name: CINQUE-62N68W Number: 31SENW County: _____

Qtrqr: SENW Sec: 31 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.096670 Longitude: -105.048090

FACILITY - API Number: 05-123- -00 Facility ID: 317682

Facility Name: CINQUE-62N68W Number: 31SENW

Qtrqr: SENW Sec: 31 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.096670 Longitude: -105.048090

CORRECTIVE ACTIONS:

1 ☒ CA# 122605

Corrective Action: Comply with Rule 603.f. Corrective action date is being backdated to the last corrective action FIR.

Date: 08/31/2015

Response: CA COMPLETED

Date of Completion: 12/18/2019

Operator Comment: Foundation did not remove the submerged line at the time of the well and battery abandonment because a nearby pipeline marker indicated that the line was operated by Kerr McGee/Anadarko. The flange and check valve on the line support the belief that this is a sales line, rather than a flowline. Kerr-McGee was able to remove the line when the gravel pit drained the area in order to mine it.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 ☒ CA# 122607

Corrective Action: Operator shall provide COGCC with documentation that equipment observed in the previous two FIR's was properly removed by 2/27/2019. Also, Operator shall provide COGCC with a scheduled plan and timeline for removal of the submerged equipment by 2/27/2019. Operator shall submit the above requirements via Form 4 Sundry Notice with attachments addressed to Reclamation Specialist Chris Binschus.

Date: 02/27/2019

Response: CA COMPLETED

Date of Completion: 12/18/2019

Operator Comment: Foundation received word from Kerr-McGee (Oxy) that they had removed the riser, as it was their equipment. Foundation sent a representative to the location to take photos, which are attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Oxy removed the riser at the location, and then let Foundation know that the work was complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: EHS Manager

Date: 12/30/2019 10:19:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402273986	FIR RESOLUTION SUBMITTED
402273999	Photo showing riser removed
402274000	Photo showing riser removed

Total Attach: 3 Files