

Pit Status Evaluation Form

Pit Overview:

Pit Name: COMMERCE RANCH "A" 1	Facility ID: 114685
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: TXO PRODUCTION CORP / 90735	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: COMMERCE RANCH INC. 'A' #1 (API 05-009-06190, Facility ID 205775, Loc ID 379116)	

County: BACA			
Township: 31S	Range: 42W	Section: 19	QQ: W2SE
Original Latitude/ Longitude: 37.328671 / -102.192009			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565452 | Date: 10/9/1985 |
| | Doc #: 596801 | Date: 3/18/1992 |
| | Doc #: 596792 | Date: 6/9/1993 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 565458 | Date: 11/23/1979 |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223928 | Date: 2/9/1998 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location. Well PA 3/18/1993, passed final inspection 6/9/1993

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a steel then fiberglass produced water tank on location. Related well was plugged 3/18/1993 and passed final inspection 6/9/1993. Pit status has been changed to closed.