

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2020

Submitted Date:

01/10/2020

Document Number:

690101675**FIELD INSPECTION FORM**Loc ID 314220 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10227Name of Operator: CHOLLA PETROLEUM INCAddress: 6688 N CENTRAL EXPRESSWAY 1610City: DALLAS State: TX Zip: 75206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Cahill, Terry	(214) 692-7052	tcahill@chollapetro.com	
OBENCHAIN THOMAS		tao@chollapetro.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285481	WELL	PR	06/30/2006	GW	099-06890	DUKE 1-18	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection. The Corrective Actions identified during this field inspection are located in the flowline and signs/ markers sections of report. Photos uploaded can be accessed via link(s) at end of report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign missing at wellhead; No sign at wellhead		
Corrective Action:	Install sign at wellhead to comply with Rule 210.b.	Date:	02/11/2020

**Emergency Contact Number:**

Comment: ECN required on wellhead sign

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 285481 Type: WELL API Number: 099-06890 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: The off location flowline (wellhead line) runs approximately 291' N-NW from the wellhead to the facility/ battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Cholla Petroleum Inc with off location flowlines.

Corrective Action: Comply with the following COGCC rule (partial description):

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402282662	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034310">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034310</a>
690101676	Aerial Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034298">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034298</a>
690101677	Facility and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034299">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034299</a>
690101678	View SE from facility to well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034300">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034300</a>
690101679	View from well to facility; no signage at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034301">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034301</a>