

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402285062

Date Received:

01/17/2020

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696501286

Inspection Date: 12/12/2019

FIR Submit Date: 12/12/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 305242

Location Name: BERNHARDT-64N66W Number: 7SESW County: \_\_\_\_\_

Qtrqr: SESW Sec: 7 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.319596 Longitude: -104.823246

### FACILITY - API Number: 05-123- -00 Facility ID: 448358

Facility Name: BERNHARDT 7-16 BATTERY Number: \_\_\_\_\_

Qtrqr: SESW Sec: 7 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.319596 Longitude: -104.823246

### CORRECTIVE ACTIONS:

1 ☒ CA# 135280

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Berms have been repaired. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 135281

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Mechanical issues have been fixed, valves have been tightened. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 135282

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 01/17/2020

Response: CA COMPLETED

Date of Completion: 01/06/2020

Operator Comment: Stained soil around tank, on berms have been removed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 1/17/2020 3:49:12 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402285062	FIR RESOLUTION SUBMITTED
402289418	Stained soil removed PIC1
402289419	Stained soil removed PIC2
402289420	Stained soil removed PIC3
402289421	Repaired berms PIC4
402289422	Repaired berms PIC5

Total Attach: 6 Files