

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2020

Submitted Date:

01/23/2020

Document Number:

699100944

FIELD INSPECTION FORM

Loc ID 317717 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 239851 | WELL | SI | 02/01/2019 | OW | 123-07639 | SPIKE STATE CC 6-11J | TA |

General Comment:

[This is a follow up inspection to prior documents # 699100436 & #699100583](#)

Location

Overall Good:

| | | | |
|----------------------|----------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|----------|--|-------|
| Emergency Contact Number: | | | |
| Comment: | Adequate | | Date: |
| Corrective Action: | | | |

| | | | |
|---------------------------|---|--|------------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds grown around wellhead need to be removed for good housekeeping. | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: 02/03/2020 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|--|--|------------------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel fence is tore apart. | | |
| Corrective Action: | Fenced to prevent access by Animals when the producing well or equipment is easily Accessible and poses a physical or health hazard. Per Rule 605.c.3. | | Date: 02/03/2020 |

| | | | |
|--------------------|-----------------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # | | |
| Comment: | Appears to be plumbed to surface. | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 239851 Type: WELL API Number: 123-07639 Status: SI Insp. Status: TA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 1/23/20 at approximately 0757 hrs, I, Inspector Adam Burns, Conducted a follow up inspection to prior documents # 699100436 & #699100583 at Spike State CC 6-11J of Noble Energy, at API # 123-07639 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds grown around wellhead need to be removed for good housekeeping. Comply with Rule 603.f .</p> <p>With a corrective date of 2/3/20.</p> <p>Panel fence is tore apart. Wellhead shall be adequately Fenced to prevent access by Animals when the producing well or equipment is easily Accessible and poses a physical or health hazard. Per Rule 605.c.3. With a corrective date of 2/3/20.</p> <p>See attached photos</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p> | burnsa | 01/23/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402292766 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045544 |
| 699100945 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045541 |