

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2020

Submitted Date:

01/27/2020

Document Number:

689901692

**FIELD INSPECTION FORM**

Loc ID 417781 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10417  
 Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC  
 Address: 113 N SANTA FE AVE  
 City: FLORENCE State: CO Zip: 81226

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
HART TIM		thart@fremontpetroleum.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415924	WELL	SI	06/19/2012	OW	043-06182	Patti 32-29	RI

**General Comment:**

[This is a location inspection.](#)  
[See attached photos and additional details within this report.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	There is storage of supplies at the location. It does not appear to be associated with operations however, the operator needs to control and maintain the site.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/28/2020
Type	OTHER		
Comment:	There is an unmarked pipe riser at the west side of the location . No LO/TO observed. Flow line risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/28/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**COGCC Comments**

Comment	User	Date
It is indicated in form 4 document #402164637 that the well will be plugged and abandoned by April 2020. It is recommended that reclamation begin soon after plugging within the spring season. The location will need to be fully recontoured and reclaimed. Operator will need to consult surface owner per rule 306.f. It is highly encourage to fence the location upon final reclamation to prevent disturbance and storage of supplies which was observed during inspection. The location will need to be controlled and maintained until final reclamation is achieved.	CostaR	01/27/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402295219	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048660</a>
689901693	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048656">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048656</a>