

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2020

Submitted Date:

01/27/2020

Document Number:

691201216**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243352	WELL	SI	06/01/2017	OW	123-11143	LAW 1-17	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Environmental**Spill/Remediation:**

Comment: COGCC personnel observed the partially buried produced water vessel had been removed from service and the excavation scar had been backfilled. As of the date of this inspection, Operator has not submitted a Form 27 for the removal of this vessel. Pursuant to Rule 905.b., Operator is required to close partially buried produced water vessels in accordance with prior approved Site Investigation and Remediation Workplan, Form 27.

Corrective Action: Operator shall submit an eForm 27, Site Investigation and Remediation Workplan, for the removal of the partially buried water vessel. The Workplan shall be submitted for prior COGCC approval and shall include a description of the proposed investigation and remediation activities in accordance with Rule 909.

Date: 02/26/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402295221	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048661
691201217	Removed vessel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048657
691201218	Backfilled Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048658