

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402025415

Date Received:
04/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Sessions, Tamra		tsessions@logosresourcesllc.com
Rowley, Darren		drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603452

Inspection Date: 12/19/2018

FIR Submit Date: 01/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 312068

Location Name: BONDAD 33-9-N33N9W Number: 6NESW County: LA PLATA

Qtrqtr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129400 Longitude: -107.870440

FACILITY - API Number: 05-067-00 Facility ID: 216555

Facility Name: BONDAD 33-9 Number: 13A

Qtrqtr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129400 Longitude: -107.870440

CORRECTIVE ACTIONS:

1 CA# 121452

Corrective Action: A long term weed control plan needs to be implemented in 2019. Multiple control methods and subsequent treatments are likely needed. Recommend contacting La Plata County weed control specialist for suggestions to manage infestations. Control weeds at the appropriate time but no later than June 1, 2019.

Date: 06/01/2019

Response: CA COMPLETED Date of Completion: 04/29/2019

Operator Comment: As per LOGOS Operating's policy, noxious weeds will continue to be sprayed annually and more often as necessary to control them.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 121453

Corrective Action: Stormwater controls and slope stabilization measures need to be installed to stabilize erosion on the well pad cut and fill slopes. Revegetation will help provide long term stabilization. Temporary erosion control measures such as natural fiber erosion control blankets, need to be installed until perennial vegetation is established.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: Stormwater controls and slope stabilization measures were completed on April 12, 2019 to stabilize erosion on the well pad cut and fill slopes. All disturbed soil was seeded to provide long term stabilization. Natural fiber erosion control blankets were installed on the cut slope until perennial vegetation can be established.

COGCC Decision: **Not Approved**

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: _____

Title: Env/Reg Technician

Date: 4/29/2019 3:53:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402025415	FIR RESOLUTION SUBMITTED
402025442	Photograph
402025446	Photograph
402025448	Photograph
402025451	Photograph
402025453	Photograph
402025457	Photograph
402025459	Photograph

Total Attach: 8 Files