

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402304563

Date Received:
02/05/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>James, Brian</u>		<u>bjames@hpres.com</u>
<u>-</u>		<u>dnr_cogccengineering@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500926
Inspection Date: 12/17/2019 FIR Submit Date: 12/18/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318568

Location Name: HAROLD-62N62W Number: 31NWSW County: _____
Qtrqr: NWS Sec: 31 Twp: 2N Range: 62W Meridian: 6
W
Latitude: 40.093010 Longitude: -104.373937

FACILITY - API Number: 05-123-00 Facility ID: 318568

Facility Name: HAROLD-62N62W Number: 31NWSW
Qtrqr: NWS Sec: 31 Twp: 2N Range: 62W Meridian: 6
W
Latitude: 40.093010 Longitude: -104.373937

CORRECTIVE ACTIONS:

1 CA# 135454

Corrective Action: Comply with Rule 1004.a. to remove (regardless of ownership) all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging (05/21/2018) the associated facility. All work should have been conducted by 8/21/2018.

Date: 08/21/2018

Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: DCP equipment has been removed.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 135455

Corrective Action: Comply with Rule 1004.a. to remove all gravel, re-contour and re-grade the access road, and perform compaction alleviation.
Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Date: 08/21/2018

Response: CA COMPLETED

Date of Completion: 02/10/2020

Operator Comment: Final Reclamation to remove all gravel, re-contour and re-grade the access road, and perform compaction alleviation is to be commenced 2/10/20.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: DCP equipment has been removed. Landowner has approved of the additional final reclamation work, which is to be done the week of 2/10/20.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian James Signed: _____

Title: Land Manager Date: 2/5/2020 3:13:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files