

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No Wellhead sign		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 03/04/2020

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 246659 Type: WELL API Number: 123-14456 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (2/4/2020) at approximately (9:30), I,(Abe Serna), Conducted an on-site inspection at (Churchill 28A #1) (PDC Energy), at (Location #327297) in (County) Colorado. While there, I observed (PR Well) During this inspection no wellhead sign was present Rule 210.b. compliance issue were observed. A follow up on this site inspection needs to be conducted. This is a summary of inspection report. Continuing Inspector Training.</p>	sernaa	02/04/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402302642	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056410
698700923	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5056405