

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402070571

Date Received:  
06/11/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

CO2Source\_Regulatory@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900259

Inspection Date: 04/26/2019

FIR Submit Date: 05/06/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 461135

Location Name: GP Number: 29 County: MONTEZUMA

Qtrqr: NWN Sec: 27 Twp: 37N Range: 17W Meridian: N  
W

Latitude: 37.440130 Longitude: -108.717050

FACILITY - API Number: 05-083- -00 Facility ID: 461197

Facility Name: GP Number: 29

Qtrqr: NWN Sec: 27 Twp: 37N Range: 17W Meridian: N  
W

Latitude: 37.440130 Longitude: -108.717050

CORRECTIVE ACTIONS:

1 ☒ CA# 124940

Corrective Action:

Date: 02/18/2019

Stormwater controls and BMPs need to be installed to stabilize erosion within the project area, including, but not limited to, stormwater management as described in Kinder Morgans BMPs for new construction on the Form 2A. This includes stabilization measures such as perimeter controls, outlet structures, silt traps, ditches, and loose, exposed soils. Stormwater and erosion controls need to be sized, selected, and installed using good engineering practices, such as those described in CDOT stormwater control manuals.

Corrective action is back-dated to date of construction to document days out of compliance.

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Kinder Morgan completed soil stabilization within the project area, including layback of slopes, returning areas to cropland and hydro mulching as demonstrated per the attached photos and current storm water BMP map.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Lopez

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 6/11/2019 11:36:16 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402070571	FIR RESOLUTION SUBMITTED
402070578	Photo Documentation
402070583	Current Storm water BMP map

Total Attach: 3 Files