

Pit Status Evaluation Form

Pit Overview:

Pit Name: SHANLINE-HENDERSON-TREON	Facility ID: 114646
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: KAISER-FRANCIS OIL COMPANY / 45898	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: SHANLINE-HENDERSON-TREON #1 (API 05-009-05142, Facility ID 205450, Loc ID 378844)	

County: BACA			
Township: 32S	Range: 41W	Section: 21	QQ: NEWSW
Original Latitude/ Longitude: 37.241833 / -102.052315			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565573 | Date: 4/2/1985 |
| | Doc #: 609630 | Date: 4/27/1998 |
| | Doc #: 200003513 | Date: 01/24/2000 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a fiberglass produced water tank on location. Associated well was plugged 6/16/1998 and passed PA inspection 1/24/2000. Pit status has been changed to closed.

