

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402265679

Date Received:  
12/17/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Rowley, Darren</u>		<u>drowley@logosresourcesllc.com</u>
<u>Farrell, Larissa</u>		<u>lfarrell@logosresourcesllc.com</u>
<u>Sessions, Tamra</u>		<u>tsessions@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901023

Inspection Date: 10/24/2019

FIR Submit Date: 11/04/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325194

Location Name: BONDAD 33-10-N33N10W Number: 14NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.101040 Longitude: -107.900790

FACILITY - API Number: 05-067-00 Facility ID: 214254

Facility Name: BONDAD 33-10 Number: 17

Qtrqtr: NWSE Sec: 14 Twp: 33N Range: 10W Meridian: N

Latitude: 37.101040 Longitude: -107.900790

CORRECTIVE ACTIONS:

1  CA# 133177

Corrective Action:

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative signature]

2  CA# 133178

Corrective Action: Revegetation and stabilization measures are needed to stabilize erosion on the well pad cut-slope.

Date: 11/22/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator Comment:

Re-seeding and stabilization measures have been installed to stabilize erosion on the well pad cut-slope.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative signature]

OPERATOR COMMENT AND SUBMITTAL

Comment:

[Empty text box for Operator Comment]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: \_\_\_\_\_

Title: Env/Reg Technician

Date: 12/17/2019 2:43:57 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402265679	FIR RESOLUTION SUBMITTED
402265701	Photo
402265703	Photo
402265704	Photos

Total Attach: 4 Files