

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/09/2020

Document Number:

688307188**FIELD INSPECTION FORM**Loc ID 317124 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236555	WELL	PR	12/01/2010	OW	121-09045	KLOEFKORN 1	PR

General Comment:

Reinspection of inspection #688306985. Free oil is still on pit from last inspection as a corrective action due 2/15/2020. Corrective action from last inspection to label tanks is due 3/18/2020. Corrective action to return call to emergency contact number on the the signage was fixed on next inspection at another well when operator texted back right away.

Inspected Facilities									
Facility ID:	236555	Type:	WELL	API Number:	121-09045	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Dec 2019 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: YES2+ feet Freeboard: YESComment:

Free oil on pit observed. Some oil has been removed however there is more free oil and stained soils that also need to be removed. The north pit berm where the skim pit used to be could be raised to be equal to other pit berms. Inspector contacted operator and left message to clean up free oil within 24 hours on the afternoon on 2/14/2020 with no response.

Corrective Action:

Remove free oil and stained soil from pit per Rule 902.c.

Date: 02/15/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402336638	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5089057
688307213	Ward & Son Alfred Kloefkorn 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5089044