

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402346984

Date Received:  
03/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Christina Pierce</u>	<u>970-263-3624</u>	<u>cpierce@Laramie-Energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201067

Inspection Date: 03/02/2020

FIR Submit Date: 03/05/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436835

Location Name: Homer Deep Unit Number: 7-23 County: \_\_\_\_\_

Qtrqtr: NESW Sec: 7 Twp: 8S Range: 98W Meridian: 6

Latitude: 39.371980 Longitude: -108.369820

FACILITY - API Number: 05-045-00 Facility ID: 436835

Facility Name: Homer Deep Unit Number: 7-23

Qtrqtr: NESW Sec: 7 Twp: 8S Range: 98W Meridian: 6

Latitude: 39.371980 Longitude: -108.369820

CORRECTIVE ACTIONS:

1  CA# 136953

Corrective Action: Comply with Rule 603.f. Lock out/tag out unused, unmarked flowline risers within 24 hours and remove unused risers within 30 days.

Date: 07/12/2019

Response: CA COMPLETED

Date of Completion: 03/17/2020

Operator Comment: Equipment for future use see attached form 4

COGCC Decision: **Not Approved**

Operator response of "Corrective Action Complete" is a notification to the State that the corrective action has

COGCC Representative:

been addressed in its entirety. Based on operator comments, corrective action does not appear to have been completed.

Operator has only indicated that equipment is for future use; Operator has not provided documentation/information identifying the risers and their intended use.

2  CA# 136954

Corrective Action:

Corrective action has two parts:  
1) Conduct maintenance to ensure risers have been properly locked-out/covered to ensure wildlife protections.  
2) Submit documentation attached to a Form 4 identifying the use of the unused equipment/risers observed on the Location.

Date: 04/05/2020

Response: CA COMPLETED

Date of Completion: 03/17/2020

Operator Comment:

Equipment for future use see attached form 4

COGCC Decision:

**Not Approved**

COGCC Representative:

Operator response of "Corrective Action Complete" is a notification to the State that the corrective action has been addressed in its entirety. Based on operator comments, corrective action does not appear to have been completed:

Sundry doc. #402346984 does not provide any information regarding the equipment. No documentation indicating that the riser observed has been locked-out/covered per the corrective action.

Corrective action required operator to identify the use of the unused equipment/risers,

Operator has only indicated that equipment is for future use; Operator has not provided documentation/information identifying the risers and their intended use.

This corrective action remains applicable.

3  CA# 136955

Corrective Action:

Two corrective actions are being applied:  
1) Comply with Rule 1003 and conduct interim reclamation on areas of the pad not needed for production. Reclamation activities, including but not limited to, compaction alleviation, recontouring, regrading and revegetation is required in accordance with Ruled 1003.b, 1003.c and 1003.e. Rules require Interim reclamation no later than 6 months post operations; A corrective action date of 1/17/2018 is being applied as this was the date reclamation was required based on operation records on file.  
2) Operator is required to submit (attached to a form 4) a figure showing areas to be reclaimed during interim reclamation activities. Figure(s) shall be submitted by 3/19/2020.

Date: 01/17/2018

Response: CA COMPLETED

Date of Completion: 03/17/2020

Operator Comment:

working with BLM for interim reclaim see attached form 4

COGCC Decision:

**Not Approved**

COGCC Representative:

Operator response of "Corrective Action Complete" is a notification to the State that the corrective action has been addressed in its entirety.

Operator has provided documentation per the CA, however Location will remain out of compliance with 1003 Rules and corrective action until Interim Reclamation activities have been completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:



I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce Signed: \_\_\_\_\_

Title: Engineering Tech Date: 3/19/2020 10:03:52 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402346984	FIR RESOLUTION SUBMITTED
402346990	corrective action

Total Attach: 2 Files