

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2020

Submitted Date:

03/19/2020

Document Number:

689803762

FIELD INSPECTION FORM

Loc ID 439603 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
 Address: 123 ROBERT S KERR AVE
 City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448056	WELL	PR	02/01/2018		057-06587	Castle 0780 5-17H20	WK

General Comment:

[COGCC Inspection Report 689803762 Summary](#)
 On Friday 3/5/2020 at approximately 13:00, I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration and Production LLC Gregory 0780 S9 Pad, at 439603 in Jackson County Colorado.
 While there, I observed a workover rig.
 During this inspection the following possible compliance issues were observed:
 Tracking occurring onto Colorado State Highway 14 from the location entrance. See photos 2-4. Install or repair required BMPs per Rule 1002.f.(2)C
 I spoke with Aran Cook about the tracking and he informed me that the tracking pad was ready to be installed and would be in place by Monday 3/9.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report 689803762.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 448056 Type: WELL API Number: 057-06587 Status: PR Insp. Status: WK

Workover

Comment: Workover on location fixing a parted rod.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Fail			No tracking pad.

Comment: [Tracking occurring onto Colorado State Highway 14 from the location entrance. Inspector spoke with Aran Cook about the tracking and he informed me that the tracking pad was ready to be installed and would be in place by Monday 3/9.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 03/05/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402347435	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100437
689803763	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100433