

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/23/2020

Submitted Date:

03/27/2020

Document Number:

688307430**FIELD INSPECTION FORM**Loc ID 317345 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Benish, Erick	(970) 630-5723	Entrulc@gmail.com	
Smith, Chris	(303) 709-6157	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258659	WELL	PR	11/01/2009	GW	121-10637	ALLEN 5	PR

**General Comment:**

Routine Inspection

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-554-0250

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 258659 CDP:

Comment:

Corrective Action:  Date:

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action:  Date:

**Wildlife BMPs:**

**Comment:**

Corrective Action:  Date:

**Comment:**

**Corrective Action:**  Date:

**On Site Inspection (305):****Surface Owner Contact Information:**

Name:  Address:

Phone Number:  Cell Phone:

**Operator Rep. Contact Information:**

Landman Name:  Phone Number:

Date Onsite Request Received:  Date of Rule 306 Consultation:

Request LGD Attendance:

**LGD Contact Information:**

Name:  Phone Number:  Agreed to Attend:

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Inspected Facilities									
Facility ID:	258659	Type:	WELL	API Number:	121-10637	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. 1//1/2020 production reported to COGCC database.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307485	Smith Energy LLC, Allen 5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107635</a>