

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/27/2020

Submitted Date:

03/29/2020

Document Number:

700400728**FIELD INSPECTION FORM**
 Loc ID 315282 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 2445 TECHNOLOGY FOREST BD #710City: THE WOODLANDS State: TX Zip: 77381**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Nicol, Michael	281-362-8600x116	mnicol@locinoil.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230563	WELL	PR	11/13/1978	GW	103-08231	FORK UNIT-FEDERAL 7-11-1-2	PR

General Comment:[COGCC Inspection Report Summary.](#)

On 3-27-2020 at approximately 17:40, inspector Rick Moran, conducted a routine inspection at Locin well Fork Unit 7-11-1-2 in Rio Blanco county.

The following compliance issues were observed:

1) Missing "911" on battery sign. Photo 3. Complete by 4-30-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400728.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on battery sign.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 04/30/2020

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	230563	Type:	WELL	API Number:	103-08231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Corrective

Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment:

Corrective

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective

Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective
ActionDate: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700400729	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5108103