

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2020

Submitted Date:

03/26/2020

Document Number:

699301243**FIELD INSPECTION FORM**Loc ID 318484 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		conor.pesicka@state.co.us	
,		rwatzman@kpk.com	All Inspections
James, Brian		bjames@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241383	WELL	SI	12/01/2017	GW	123-09172	PRESTON 43-18	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Wees overgrown on access rd.		
Corrective Action	Comply with Rule 603.f	Date:	04/02/2020

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign has older operator information, current operator should replace sign ASAP.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241383 Type: WELL API Number: 123-09172 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 03/26/2020 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kaufmann location:</p> <p style="text-align: right;">Preston 43-18 at API #05-123-09172 in Weld County Colorado.</p> <p>While there, I observed shut in wellsite.</p> <p>Form 10 Doc. # 402018972 was submitted on 5-1-2019 and is in process.</p> <p>During this inspection the following compliance issues were observed:</p> <p>603.f housekeeping: dead weeds along access road, CA date 4-2-2020 see photo 1.</p> <p>210.b WH sign has old operator information and should be updated ASAP.</p> <p>See photo 2.</p> <p>Location is wet, weather is cloudy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	03/26/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402353875	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106451
699301244	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106448