

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402018307

Date Received:

04/23/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Distribution, Evergreen</u>		<u>cogcc.evergreen@enrllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695100170
Inspection Date: 02/11/2019 FIR Submit Date: 02/11/2019 FIR Status: _____

Inspected Operator Information:

Company Name: PIONEER NATURAL RESOURCES USA INC Company Number: 10084
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

LOCATION - Location ID: 307800

Location Name: LORENCITO-634S66W Number: 6NENW County: LAS ANIMAS
Qtrqtr: NENW Sec: 6 Twp: 34S Range: 66W Meridian: 6
Latitude: 37.117460 Longitude: -104.824170

FACILITY - API Number: 05-071- -00 Facility ID: 256921

Facility Name: LORENCITO Number: 3-6-34-66
Qtrqtr: NENW Sec: 6 Twp: 34S Range: 66W Meridian: 6
Latitude: 37.117460 Longitude: -104.824170

CORRECTIVE ACTIONS:

1 ☒ CA# 122435

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.

Date: 02/13/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator Comment: The source of the sheen looks to have come from a vehicle or drip truck. All work has been remediated and half a yard of soil was removed and hauled to our contaminated soil remediation area at the Burro facility. We took precautionary steps and added double wall tank and hard lined from separator to tank to prevent produced water to discharge on soil. Produced water in vessel was checked for contaminants and none were

present. A form 4 #401948015 was submitted as requested by Jason Kosola and approved.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: _____

Title: Regulatory Specialist

Date: 4/23/2019 1:53:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402018307	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files