

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2020

Submitted Date:

04/10/2020

Document Number:

679602460**FIELD INSPECTION FORM**Loc ID 306589 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289922	WELL	PR	03/06/2008	GW	123-24957	HEINRICY 11-7U	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: 04/20/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 289922 Type: WELL API Number: 123-24957 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SI; pilot offCorrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

\*\*Weather Conditions: sunny, dry ground

On Friday, April 10, 2020 at approximately 09:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at HEINRICY 11-7U (PDC Energy), at API #: 05-123-24957 in WELD COUNTY Colorado.

While there, I observed a shut in wellhead.

During this inspection the following possible compliance issues were observed:

1. Appears to be stained soil underneath mast valve. CONDUCT MAINTENANCE ON EQUIPMENT, CLEANUP STAINED MATERIAL AND REVIEW SELF INSPECTION PROCESSES PER RULE 1002.F.(2).D. (Corrective Action Date: April 20, 2020) See attached photo #3.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

santistb

04/10/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402368010	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120919">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120919</a>
679602461	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120912</a>