

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2020

Submitted Date:

04/07/2020

Document Number:

689803941

**FIELD INSPECTION FORM**

Loc ID 312968 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10407  
Name of Operator: ANTLER ENERGY LLC  
Address: PO BOX 104  
City: BAGGS State: WY Zip: 82321

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223072	WELL	PR	08/26/1981	GW	081-06434	POWDER WASH FEDERAL 28-3	PR

**General Comment:**

COGCC Inspection Report 689803941 Summary  
On Tuesday 04/07/2020 at approximately 11:40, I, Inspector Emily Waldron, conducted a field inspection at Antler Energy LLC Powder Wash Federal 28-3, at 05-081-06434 in Moffat County Colorado.  
While there, I observed production.  
During this inspection the following possible compliance issues were observed:  
Stained soil at pump jack. See photo 2. Comply with Rule 603.f, securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d, and properly dispose of oily waste in accordance with 907.e by 4/21/2020.  
Fenced area with oily soil. See photo 3. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff by 10/10/2018.  
Two pits on location. See photos 4 and 5. Two pit ids with this location 100421, 100424. No pit permit on file. Please provide an update to kris.neidel@state.co.us on the status of these pits. Netting on pits should be maintained in good working order prior to use of pit. Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 903.a by 11/24/2016.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report 689803941.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	307-380-7616		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at pump jack.		
Corrective Action:	Comply with Rule 603.f. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly dispose of oily waste in accordance with 907.e		Date: <u>04/21/2020</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 223072 Type: WELL API Number: 081-06434 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pumping.

Corrective Action:

Date:

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Land Treatment		40.889890	-108.298900
Comment	Fenced area with oily soil.			
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.			Date: <u>10/10/2018</u>

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Two pit ids with this location 100421, 100424. No pit permit on file.

Corrective Action \_\_\_\_\_

Date: 11/24/2016

**Please provide an update to kris.neidel@state.co.us on the status of these pits. Netting on pits should be maintained in good working order prior to use of pit. Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 903.a.**

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402368675	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121685">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121685</a>
689803942	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5121680</a>