

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402378094

Date Received:

04/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

jake Forsman

Phone

970-882-5541

Email

CO2Source Permitting@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901437

Inspection Date: 02/20/2020

FIR Submit Date: 02/24/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313490

Location Name: MCELMO DOME UNIT 23-37-18-N37N18W Number: 23SWSW County: \_\_\_\_\_

Qtrqtr: SWS Sec: 23 Twp: 37N Range: 18W Meridian: N  
W

Latitude: 37.444647 Longitude: -108.809829

FACILITY - API Number: 05-083-00 Facility ID: 313490

Facility Name: MCELMO DOME UNIT 23-37-18-N37N18W Number: 23SWSW

Qtrqtr: SWS Sec: 23 Twp: 37N Range: 18W Meridian: N  
W

Latitude: 37.444647 Longitude: -108.809829

CORRECTIVE ACTIONS:

1 CA# 136676

Corrective Action: Conduct revegetation within portions of the interim reclamation area with bare soils and sparse vegetative cover by 4/17/2020. Soil testing and amendment are likely needed for successful revegetation.

Date: 04/17/2020

Additionally, control weeds at the appropriate time and no later than 6/1/2020. Additional treatments are likely needed to control infestation.

Response: CA COMPLETED

Date of Completion: 04/22/2020

Operator  
Comment:

Soil samples were collected and submitted to a lab to be analyzed for soil characteristics and nutrient levels. The western and northern barren areas within the interim reclamation area tested much higher for salts than the eastern side. The barren areas within the northern and western sides of the interim reclamation areas have had one of two rounds of soil amendments applied. Due to the high salt contrations in these areas, it is recommended that the areas sit idle to allow time for the amendments to lower the salt concentrations before proceeding with the nutrient amendments and reseedling. Additional nutrients will be applied to this area in mid-May 2020 and re-seeding/mulching will occur immediately afterward.

The eastern side of the interim reclamation area has been amended, re-seeded and mulched. The mulch will act as a storm water control measure to minimize erosion.

The Russian Knapweed and the Salt Cedar tree were removed. The YB-2 Well Location will be added to the Kinder Morgan weed spraying rotation.

COGCC Decision:

\_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

The soil amendments are currently working on the salt concentrations on the western and northern sides of the YB-2 Well Location. Additional nutrients and re-seeding will be completed by 5/15/2020.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jake Forsman

Signed:

\_\_\_\_\_

Title: EHS Specialist

Date: 4/22/2020 4:23:41 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402378252	Photo Log
-----------	-----------

Total Attach: 1 Files