

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402385599

Date Received:
04/30/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincesantistevan@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Duran, Alicia</u>		<u>alicia.duran@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102727
Inspection Date: 04/21/2020 FIR Submit Date: 04/21/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308442

Location Name: GOLDEN EAGLE-633S67W Number: 20SWNE County: LAS ANIMAS
Qtrqr: SWNE Sec: 20 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.161324 Longitude: -104.906271

FACILITY - API Number: 05-071-00 Facility ID: 272123

Facility Name: GOLDEN EAGLE Number: 20-07
Qtrqr: SWNE Sec: 20 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.161324 Longitude: -104.906271

CORRECTIVE ACTIONS:

1 CA# 138212

Corrective Action:

Date: 05/01/2020

Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector.

Response: CA COMPLETED

Date of Completion: 04/27/2020

Operator Comment: The sand was removed from location in accordance with the Sand - Premium White MSDS. See attached MSDS for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 138213

Corrective Action: COMPLY WITH RULE 603.f.

Date: 05/06/2020

Response: CA COMPLETED

Date of Completion: 04/27/2020

Operator Comment: The exhaust pipe extension was removed from location. The red hose was re-connected to the well head as this is the fuel gas line to keep the PC engine running. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 138214

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 05/05/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator Comment: The guy line marker was re-installed. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 138215

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/26/2020

Response: CA COMPLETED

Date of Completion: 04/27/2020

Operator Comment: The impacted soil around the PC engine was cleaned up and removed from location. The fluid accumulation in the containment below the PC engine was removed and the skid was cleaned up. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/30/2020 10:09:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402385722	Photo Log
402385743	MSDS

Total Attach: 2 Files