

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 1: APPROXIMATELY 3 YARDS OF CLEAN FRAC SAND WAS REMOVED FROM LOCATION AND DISPOSED OF THROUGH THE CONTAMINATED SOIL PROCESS.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 2: THE UNUSED EXHAUST HOSE EXTENSION WAS REMOVED FROM LOCATION.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 3: THE RED HOSE WAS RE-CONNECTED TO THE WELL HEAD AS THIS IS THE FUEL GAS LINE TO RUN THE PC ENGINE.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 4: THE RED HOSE WAS RE-CONNECTED TO THE WELL HEAD AS THIS IS THE FUEL GAS LINE TO RUN THE PC ENGINE.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 26, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 5: THE LEAK ON THE PC ENGINE WAS REPAIRED. THE IMPACTED SOIL/GRAVEL ON THE GROUND WAS CLEANED UP AND REMOVED FROM THE LOCATION.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 6: THE LEAK ON THE PC ENGINE WAS REPAIRED. THE IMPACTED SOIL/GRAVEL ON THE GROUND WAS CLEANED UP AND REMOVED FROM THE LOCATION.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 7: THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT ON THE PC ENGINE AND THE SKID WAS CLEANED UP.

GOLDEN EAGLE 20-07 API# 05-071-08052 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 29, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102727



PHOTO 8: THE DOWNED GUY LINE MARKER WAS REINSTALLED.