

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402389849

Date Received:
05/05/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Blake Ford

970-776-6617

bford@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697001138

Inspection Date: 04/29/2020

FIR Submit Date: 04/29/2020

FIR Status: _____

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC

Company Number: 10459

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 431077

Location Name: River Bluffs Multi Well Pad Number: 18-13 County: _____

Qtrqr: SWNE Sec: 13 Twp: 6N Range: 68W Meridian: 6

Latitude: 40.489097 Longitude: -104.949351

FACILITY - API Number: 05-069- -00 Facility ID: 431077

Facility Name: River Bluffs Multi Well Pad Number: 18-13

Qtrqr: SWNE Sec: 13 Twp: 6N Range: 68W Meridian: 6

Latitude: 40.489097 Longitude: -104.949351

CORRECTIVE ACTIONS:

1 CA# 138480

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 07/01/2020

Response: CA COMPLETED

Date of Completion: 05/05/2020

Operator Comment: Pursuant of COGCC Rule 603.h.(2)E, Extraction Oil and Gas is requests a variance by way of an alternative compliance plan. As a response to low commodity prices, all of Extraction's vertical sites will be shut-in through 2020. In addition to these measures, the River Bluffs tanks will be bottomed out completely and "out of service" stickers will be placed on the tanks. Once this tank battery is brought back online a steel tanks berm will replace the earthen berm.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 138481

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 07/01/2020

Response: CA COMPLETED

Date of Completion: 05/05/2020

Operator Comment: Pursuant of COGCC Rule 603.h.(2)E, Extraction Oil and Gas is requests a variance by way of an alternative compliance plan. As a response to low commodity prices, all of Extraction's vertical sites will be shut-in through 2020. In addition to these measures, the River Bluffs tanks will be bottomed out completely and "out of service" stickers will be placed on the tanks. Once this tank battery is brought back online a steel tanks berm will replace the earthen berm.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Blake Ford

Signed: _____

Title: Environmental Supervisor

Date: 5/5/2020 10:16:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files