

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402362618

Date Received:

04/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Christina Pierce

970-263-3626

cpierce@Laramie-Energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692401347

Inspection Date: 09/06/2019

FIR Submit Date: 09/16/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324314

Location Name: CC Number: 0610-24-43 County: _____
Pad

Qtrqtr: SESW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.533117 Longitude: -108.207480

FACILITY - API Number: 05-045- -00 Facility ID: 324314

Facility Name: CC Number: 0610-24-43
Pad

Qtrqtr: SESW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.533117 Longitude: -108.207480

CORRECTIVE ACTIONS:

1 ☒ CA# 130642

Corrective Action: Install Reclamation in Areas no longer needed for Use, Production, Drilling or Subsequent Operations; including Fill Slopes in revegetation plans; installing appropriate BMPs to Stabilize Areas until Vegetation establishes. Reclamation Activities should be complete by 6/15/2018.

Date: 06/15/2018

Response: CA COMPLETED

Date of Completion: 10/15/2019

pad was interim reclaimed

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC Representative: CA Stands. CA Date is 6/15/18. Site is Out of Compliance.

2  CA# 130643

Corrective Action: CA#1) Install or repair required BMPs in accordance with Good Engineering Practices per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/15/2018

CA#2) Stabilize Fill Slopes; incorporate with Interim Reclamation CA Activities, installing Appropriate BMPs to stabilize slopes until vegetation establishes. Refer to Photos attached.

Response: CA COMPLETED

Date of Completion: 10/15/2019

Operator Comment: no BMP required pad was interim reclaimed

COGCC Decision: **Not Approved**

COGCC Representative: CA Stands. CA Date is 6/15/18. Site is Out of Compliance.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed:

Title: Engineering Tech

Date: 4/6/2020 10:19:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402362618	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files