

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2020

Submitted Date:

04/22/2020

Document Number:

696102775**FIELD INSPECTION FORM**Loc ID 331974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269330	WELL	SI	06/01/2017	GW	123-21659	WARDLAW 35-24	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (331974, 330167, 330166).
(Well(s): 2: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (329660).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	<p>Centralized Battery serves 3 Location IDs (331974, 330167, 330166). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (329660). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.</p>				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 269330 Type: WELL API Number: 123-21659 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Shut-In | SI.

Yellow LTSI tag posted at well.

Locked-Out, Tagged-Out | LOTO.

COGCC records indicate last production: 05/2017.

Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42.

Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Refer to Rule 326.b.

Corrective Action:

Well is overdue for Mechanical Integrity Test.

Produce well after performing successful mechanical integrity test per Rule 326 or plug well.

To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Refer to Rule 326.b.

Corrective Action Date: 07/21/2020. Extended due to COVID.

Date: 07/21/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 04/22/2020 at approximately 11:16 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WARDLAW-66N64W /35SEnw Location ID: 331974 Well Name: Wardlaw 35-24 API: 05-123-21659 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (331974, 330167, 330166). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (329660). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed. 1.) Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Refer to Rule 326.b.</p> <p>Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Refer to Rule 326.b.</p> <p>Corrective Action Date: 07/21/2020. Extended due to COVID.</p> <p>A follow up on this site inspection will be conducted to ensure compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402378469	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130304
696102780	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5130299