

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2020

Submitted Date:

05/08/2020

Document Number:

688307803

FIELD INSPECTION FORMLoc ID 317124 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 94300

Name of Operator: WARD & SON* ALFRED

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Young, Rob		rob.young@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236555	WELL	SI	02/01/2020	OW	121-09045	KLOEFKORN 1	SI

General Comment:

Reinspection of oil on pit from inspection #688307188, oil still on pit, pit berms eroding into field and pasture, stained soil in treater shed at flowline, subsidence near produced water tanks and pit pipe outlet (see attached photos). Submit Form 19I for spill on pit.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 308-280-0100

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Valves/pipes leaking inside treater shed. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/29/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	Free oil spill on Kloefkorn pit found 5/4/2020, ~40 bbls.		
Corrective Action:	Report spill or release of E&P waste or produced fluids (Form 19I). Remove free fluids and contact COGCC EPS staff per Rule 906.b.		Date: 05/05/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Vertical Heater Treater	# 1		corrective date
Comment:	bermed, shed		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: electric		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2				,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2				,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	236555	Type:	WELL	API Number:	121-09045	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					
Compaction	Fail					

Comment: Pit berms eroding into field and pasture (see attached photos). Subsidence at produced water tanks.

Corrective Action: Install/maintain stormwater BMPs to prevent offsite sediment transport. Maintain compaction at tanks to support tank.

Date: 05/29/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Free oil on pit observed. Some oil has been removed however there is more free oil and stained soils that also need to be removed. The north pit berm where the skim pit used to be could be raised to be equal to other pit berms. Inspector contacted operator and left message to clean up free oil within 24 hours on the afternoon on 2/14/2020 with no response. 5/4/2020-Still free oil on pit. Vac truck was at the nearby Wright pit and removed more oil from Kloefkorn pit on way out to empty truck. See attached photos.

Corrective

Remove free oil and stained soil from pit per Rule 902.c.

Date: 02/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688307827	Ward & Son Kloefkorn 1	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146159