

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/08/2020

Document Number:

688307824**FIELD INSPECTION FORM**Loc ID 317166 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	COGCC EPS
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Leonard, Mike		mike.leonard@state.co.us	COGCC Acting FIU Manager
Axelson, John		john.axelson@state.co.us	COGCC Action EPS Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236964	WELL	PR	12/13/1979	OW	121-09464	WRIGHT 31-1	SI

General Comment:

Reinspection of 5/4/2020 spill, pit clean

Inspected Facilities									
Facility ID:	236964	Type:	WELL	API Number:	121-09464	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>SI for spill. Check produced water tanks for oil prior to start up.</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined: _____

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective _____

Date: _____

Fencing:

Fencing Type: _____

Fencing Condition: _____

Comment: _____

Corrective _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

See Spill section of inspection #688307804 for removal of free fluids observed on pit. Stained soil ring remains inside pit walls that needs to be removed and properly disposed of (see attached photos). Pit berms are eroding into adjacent field and pasture (see attached photo).

Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS. Maintain pit berms.
Date: 05/27/2020

Corrective Action

Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS. Maintain pit berms.

Date: 05/27/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688307825	Ward & Son Alfred Wright 31-1	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146173