

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402395458

Date Received:

05/12/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

SanJuanCOGCC@bp.com

sabre.beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901516

Inspection Date: 03/10/2020

FIR Submit Date: 03/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333112

Location Name: WIRT GAS UNIT D-N32N7W Number: 8NESW County: LA PLATA

Qtrqtr: NESW Sec: 8 Twp: 32N Range: 7W Meridian: N

Latitude: 37.028284 Longitude: -107.635882

FACILITY - API Number: 05-067- -00 Facility ID: 213846

Facility Name: WIRT D Number: 1

Qtrqtr: NESW Sec: 8 Twp: 32N Range: 7W Meridian: N

Latitude: 37.028284 Longitude: -107.635882

CORRECTIVE ACTIONS:

1 CA# 137154

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: BPX retains a professional weed control contract company to treat weeds annually. This location received chemical treatment for weeds on 7/19/16, 7/21/17, 6/11/18 and 9/3/2019. Most recently weed debris has been manually removed and properly disposed of. See attached. Documentation of treatment provided from contract company on chemical application can be provided upon request. Corrective action has been addressed and attempts to control weeds is being performed on an annual basis. Eradication of weeds on locations is an extended process as Thistle seed banks are viable for 5+ years. BPX has plans to continue annual weed

treatment programs performing efforts to address weeds. FIRR # previously filed 402360414

COGCC Decision: _____

COGCC
Representative:

--

2 CA# 137155

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/15/2020

Operator
Comment:

Armoured rock run down installed for stormwater controls see attached.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions completed. Attachment option within FIRR system not functioning so unable to attach completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 5/12/2020 6:42:59 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files