

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/08/2020

Document Number:

688307824**FIELD INSPECTION FORM**Loc ID 317166 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	COGCC EPS
Axelson, John		john.axelson@state.co.us	COGCC Action EPS Manager
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Leonard, Mike		mike.leonard@state.co.us	COGCC Acting FIU Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236964	WELL	PR	12/13/1979	OW	121-09464	WRIGHT 31-1	SI

General Comment:

Reinspection of 5/4/2020 spill, pit clean

Inspected FacilitiesFacility ID: 236964 Type: WELL API Number: 121-09464 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI for spill. Check produced water tanks for oil prior to start up.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: ☐Pit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: Corrective Action: Date: 05/27/2020

See Spill section of inspection #688307804 for removal of free fluids observed on pit. Stained soil ring remains inside pit walls that needs to be removed and properly disposed of (see attached photos). Pit berms are eroding into adjacent field and pasture (see attached photo).

Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS. Maintain pit berms.
Date: 05/27/2020

Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS. Maintain pit berms.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402394129	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146185
688307825	Ward & Son Alfred Wright 31-1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146173