

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402389064

Date Received:

05/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102498

Inspection Date: 03/31/2020

FIR Submit Date: 03/31/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308800

Location Name: APACHE CANYON-634S67W Number: 7SWNW County: LAS ANIMAS

Qtrqr: SWN Sec: 7 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.099561 Longitude: -104.936796

FACILITY - API Number: 05-071- -00 Facility ID: 282124

Facility Name: APACHE CANYON Number: 7-5

Qtrqr: SWN Sec: 7 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.099561 Longitude: -104.936796

CORRECTIVE ACTIONS:

1 ☒ CA# 137638

Corrective Action: COMPLY WITH NTO AND RULE 603.f.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

The riser is an active low point drain. The riser was labeled as such for clarity. See attached photo log for details.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

2 ☒ CA# 137639

Corrective Action: COMPLY WITH RULE 603.f.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: The piece of equipment that the inspector found on the ground is the belt guard to the pumping unit. The guard was removed to service the clutch. The belt guard was placed back over the belts, this equipment is in use.

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

3 ☒ CA# 137640

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: The fluid accumulation in the liquid ring containment was removed and the skid was cleaned. Maintenance was conducted to stop the leak. See attached photo log for details.

COGCC Decision: Not Approved

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/4/2020 3:15:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402389064	FIR RESOLUTION SUBMITTED
402389108	Photo Log

Total Attach: 2 Files