

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2020

Submitted Date:

05/19/2020

Document Number:

689501050

FIELD INSPECTION FORMLoc ID 433548 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
General, All inspections		cogccinspection@pdce.com	All PDC inspection
, Spills&Remediations		COGCCSpillRemediation@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453141	SPILL OR RELEASE	AC	12/15/2017		-	Phelps 12-32NHZ	EI

General Comment:

This is an environmental inspection of spill ID 453141 reported 11/26/2017 -spill remains open in COGCC database. No surface impacts were observed in the spill area. Operator is directed to submit a Form 19 with documentation for spill closure. Photos attached to document location at time of inspection.

Inspection of spill area only and not of nearby battery/production facilities or of any well heads. Any corrective actions from previous inspections that have not been addressed are still applicable.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: COGCC Spill ID 453141 (reported 11/26/2017) remains open in the COGCC database. Spill documents report that 2 bbls of oil was released onto the well pad surface due to sump overflow. No surface impacts were observed in this area (photos attached).

Corrective Action: Submit a Supplemental Form 19 including a closure request and supporting documentation. If closure of this spill cannot be completed by corrective action deadline then a Form 27 Site Investigation and Remediation Workplan shall be created for this spill.

Date: 07/02/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402402267	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154580
689501051	Field Photo 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154574
689501052	Field Photo 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154575
689501053	Field Photo 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154576