



Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Unmarked tanks		
Corrective Action:	Corrective Action Install sign to comply with Rule 210.b. Corrective Action Date, 6/15/2020 See attached photo #. 2		Date: 06/15/2020
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Unmarked tanks		
Corrective Action:	Corrective Action Install sign to comply with Rule 210.b. Corrective Action Date, 6/15/2020 See attached photo #. 2		Date: 06/15/2020
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	(Dead weeds), Location is within a designated setback location		
Corrective Action:	remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 6/1/2020 See attached photo #. 1		Date: 06/01/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:	Inadequate berms around chemical tank(s) Repair or install berms or other secondary containment devices per Rule 906.d.(1). Corrective Action Date, 6/15/2020. See attached photo #. 1		
Corrective Action:	Install berms or other secondary containment devices per Rule 906.d.(1). Corrective Action Date, 6/15/2020. See attached photo #. 1		Date: 06/15/2020
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment: <a href="#">Appears to be plumbed to surface</a>		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	BV FIBERGLASS		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berm with crude oil tanks</a>				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.802202,-104.236499
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 279864 Type: WELL API Number: 001-09552 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday May 12, 2020 at approximately 9:30 am I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Vicki 1, Smith oil properties, at API# 001-09552 in Adams County Colorado.                      While there, I observed Shut in well                      Unmarked tank and unmarked wellhead, Corrective Action Install sign to comply with Rule 210.b. Corrective Action Date, 6/15/2020 See attached photo #. 2                      (Dead weeds), Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 6/1/2020 See attached photo #. 1                      Inadequate berms around chemical tank(s) Repair or install berms or other secondary containment devices per Rule 906.d.(1). Corrective Action Date, 6/15/2020. See attached photo #.1                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	05/19/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402401779	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154065</a>
700900079	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154062">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154062</a>