

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/29/2020

Submitted Date:

06/01/2020

Document Number:

700401758**FIELD INSPECTION FORM**
 Loc ID 314964 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Sanford, Anita | | atlx@chevron.com | |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 229988 | WELL | PR | 11/04/1974 | OW | 103-07647 | FEE 95X | PR |

General Comment:

On 5-29-2020 inspector Rick Moran conducted a routine inspection at Chevron well Fee 95X in Rio Blanco county.

The following compliance issues were observed:

- 1) Fluid in cellar. Photo 2. Complete by 7-1-2020.
- 2) Gas leaking at surface casing. Photo 3. Complete by 9-1-2020.

This is a summary of inspection report 700401758.

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911

Corrective Action: _____ Date: _____

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Submersible Pump | # 1 | | |
| Comment: | Gas leaking at surface casing. | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 09/01/2020 |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 229988 | Type: WELL | API Number: 103-07647 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR | | | |
| Corrective Action: | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms | Pass | | | Material Handling And Spill Prevention | Fail | |

Comment: [Fluid in cellar.](#)Corrective Action: [Properly treat or dispose of oily waste in accordance with 907.e.](#)

Date: 07/01/2020

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700401759 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5163684 |