

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs reflect previous operator. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/09/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused signage on location. See attached photo..		
Corrective Action:	Comply with Rule 603.f.	Date:	09/09/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 415622 Type: WELL API Number: 123-31134 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

Facility ID: 415908 Type: WELL API Number: 123-31207 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: cloudy, wet ground On Tuesday, June 9, 2020 at approximately 11:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at CURTIS 23-25, 36-25 (PDC Energy), at location #: 415551 in WELD COUNTY Colorado. While there, I observed shut in wellheads. During this inspection the following possible compliance issues were observed: 1. Wellhead signs reflect previous operator. INSTALL SIGN TO COMPLY WITH RULE 210.E. (Corrective Action Date: September 9, 2020) See attached photos #1, 3. 2. Unused equipment on location (signage). REMOVE AND COMPLY WITH RULE 603.F. (Corrective Action Date: September 9, 2020) See attached photo #5. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	06/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602836	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169917