

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2020

Submitted Date:

06/10/2020

Document Number:

700401909

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 315333 _____ Moran, Rick _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 34720
 Name of Operator: GORDON ENGINEERING INC
 Address: PO BOX 3525
 City: GRAND JUNCTION State: CO Zip: 81502
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Gordon, John	970-618-0811	johngordon1gordon@yahoo.com	President
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230645	WELL	PR	03/01/2020	GW	103-08313	FEDERAL 24-1	PR

General Comment:

On 6-9-2020 inspector Rick Moran conducted a follow up inspection at Gordon Engineering well Federal 24-1 in Rio Blanco county of FIR documents:

- 1) 700400544 dated 3-18-2020.
- 2) 700401215 dated 4-24-2020.

The following compliance issues are uncompleted:

- 1) "911" missing on well head sign. Photo 3. Complete by 4-19-2020.

This is a summary of inspection report 700401909.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Missing "911" on well head sign.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Missing "911" on well head sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/19/2020

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230645 Type: WELL API Number: 103-08313 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401911	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171226