

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2020

Submitted Date:

06/10/2020

Document Number:

696201378

**FIELD INSPECTION FORM**Loc ID 335887 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jcobb@bry.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335887	LOCATION	AC			-	Chevron F06 696	RI

**General Comment:**

On 6/9/2020 Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Berry Petroleum LLC's Chevron F06 696 Location in Garfield County, Colorado.

This inspection is also a followup to #696201167 to determine compliance with the following corrective action:  
603.f: Storage of unused equipment

It was observed in this inspection that corrective actions have not been addressed.

Refer to the "Good Housekeeping" section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	<p>Previous inspection observed unused equipment (t-posts) stored on the southeast end of the Location. Operator was required to comply with Rule 603.f.</p> <p>It was observed in this inspection that unused equipment remains stored on the Location: Corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 603.f	Date:	05/08/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 335887 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402418822	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171330">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171330</a>
696201379	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171314">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5171314</a>