

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2020

Submitted Date:

06/24/2020

Document Number:

700900179**FIELD INSPECTION FORM**Loc ID 320215 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 5950 CEDAR SPRINGS ROADCity: DALLAS State: TX Zip: 75235**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEECHERL, ARTHUR	214-728-1840	Regulatory@verdadoil.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203076	WELL	PR	01/01/2020	GW	001-08482	EDNA 1	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	Adequate		
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Visual Impact Mitigation.		
Corrective Action:	Paint over graffiti on fence per Rule 804. Corrective Action Date 8/24/2020. See attached photo #.3		Date: 08/24/2020
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	150bbbs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berm with Crude tank.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.975238,-104.703719	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 203076 Type: WELL API Number: 001-08482 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: Appears to be plumbed to surface.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b></p> <p>On Friday June 19, 2020 at approximately 8:45am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Edna 1, Verdad Resources, at API #001-08482 in Adams County Colorado.</p> <p>While there, I observed Production well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Visual Impact Mitigation. Paint over graffiti on fence per Rule 804. Corrective Action Date 8/24/2020. See attached photo #.3</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	06/24/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402430342	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5182865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5182865</a>
700900180	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5182859">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5182859</a>