

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2020

Submitted Date:

07/17/2020

Document Number:

690200426**FIELD INSPECTION FORM**Loc ID 467285 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 55098Name of Operator: MCCOY PETROLEUM CORPORATIONAddress: 9342 E CENTRAL AVECity: WICHITA State: KS Zip: 67206-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HAMPEL SCOTT		scott@mccoypetroleum.com	
REINHARDT BRENT		brent@mccoypetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467643	WELL	PR			017-07813	ALC 1548 1-23	RI

General Comment:

This is an interim reclamation inspection of the ALC 1548 #1-23 location.
See attached photos and additional details within this report.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Non-Cropland

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass

Comment: There is barb wire fence around the location.

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ Pass

Comment: Soils are segregated.

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____ Fail

Comment: The soil piles are not maintained and protected from degradation of weeds and erosion.

Corrective Action: Comply with 1002.c Date: 07/31/2020

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment: _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____ Pass

Comment: _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____ Pass

Comment: _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment: The pits must be backfilled and reclaimed within 6 months of drilling and completion activities.

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment: _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment A form 4 notice for interim reclamation was provided for a commence date of 7/13/2020.
Interim reclamation has not been performed as of date of this inspection.

Corrective Action Date _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are inadequate erosion controls at the location. The soil is not stabilized and there is wind erosion occurring which is transporting the sandy soil offsite. BMP's must be implemented in accordance with good engineering practice and must be maintained.

Corrective Action: Comply with 1002.c
Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/31/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
All unused disturbed areas must be recontoured, properly decompacted by cross ripping to a depth of 18 inches, have an adequate seedbed prepared, and then seeded with a seed mixture that reflects the surrounding vegetation. Erosion controls must be implemented that stabilizes the seeded soil.	CostaR	07/17/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402445772	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198772
690200426	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203317
690200427	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198767