



99999999

**GAS CONSERVATION COMMISSION
LD INSPECTION REPORT**☐ NOTICE OF UNSATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100☒ NOTICE OF SATISFACTORY INSPECTION

API No. 05-123-05553

LEASE NAME: Steckel #1

LOCATION: SWSW-14-8N-66W

OPERATOR: Anschutz USA

DATE: 3/5/98


INSPECTOR: Dunkelke

Insp. Type: HR Insp. Status: PA PA: Y N Pass/Fail: P F Viol.: Y N NOV: Y N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

COGCC

MAR-9-98

RECEIVED

CORRECTIVE ACTION REQUIRED: No surface disturbances found

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00738417