

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Other	# 1				
Comment:	50 gallon drum not in secondary containment				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date:	08/28/2020
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 428988 Type: WELL API Number: 001-09750 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (Tuesday) (07/14/2020) at approximately (11:30am), I, Inspector (Keith Huck), conducted an on-site inspection at (Ikey#1) (Charles P. Dunning), at (Location#428987) in (Adams County) Colorado. While there, I observed (Pumpjack) During this inspection the following possible compliance issues were observed: 2nd 50 gallon drum not in secondary containment. Repair or install berms or other secondary containment devices per Rule 906.d.(1). Corrective Action Date 08/28/2020. See Photo#2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	huckk	07/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402456053	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213438
687400817	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213428