

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Unmarked tanks and battery, Sign not posted or information inaccurate at well(s)or battery		
Corrective Action:	Install sign per Rule 210.b.Corrective Action Date 8/1/2020. See attached photo #1.	Date:	08/01/2020
Emergency Contact Number:			
Comment:	Unmarked tanks and battery, Sign not posted or information inaccurate at well(s)or battery		
Corrective Action:	Install sign per Rule 210.b.Corrective Action Date 8/1/2020. See attached photo #1.	Date:	08/05/2020
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 8/14/2020. See attached photos #1 through 3.	Date:	08/14/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	pipe		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Separator # 1			
Comment:			
Corrective Action:			Date:
Type: Bird Protectors # 2			
Comment:			Netting on open tanks inadequate.
Corrective Action:			Date: 08/14/2020
Type: Bradenhead # 1			
Corrective Action:			Netting on open tanks inadequate. Wildlife protections devices not adequate. Wildlife protections devices not adequate, Install or repair wildlife protection equipment per rule 324 A.a Corrective action date 8/14/2020 See attached photos #4 through 10.

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:	Netting on open tanks inadequate. Wildlife protections devices not adequate. Wildlife protections devices not adequate, Install or repair wildlife protection equipment per rule 324 A.a Corrective action date 8/14/2020 See attached photos #4 through 10.				
Corrective Action:	Netting on open tanks inadequate. Wildlife protections devices not adequate. Wildlife protections devices not adequate, Install or repair wildlife protection equipment per rule 324 A.a Corrective action date 8/14/2020 See attached photos #4 through 10.			Date:	08/14/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berm with Crude tank.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.000428,-104.544425
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202777 Type: WELL API Number: 001-08182 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday July 31, 2020 at approximately 9:50am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Coan #1, SMITH OIL PROPERTIES INC, at API #001-08182 in Adams County Colorado. While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 8/14/2020. See attached photos #1 through 3. Unmarked tanks and battery, Sign not posted or information inaccurate at well(s) or battery. Install sign per Rule 210.b. Corrective Action Date 8/1/2020. See attached photo #1. Bull plug missing from load line. Location is within a designated setback location, bull plug or cap all load lines per Rule #604.c.(2)O. Corrective action Date 8/7/2020. See attached photo #11. Netting on open tanks inadequate. Wildlife protections devices not adequate. Wildlife protections devices not adequate, Install or repair wildlife protection equipment per rule 324 A.a Corrective action date 8/14/2020 See attached photos #4 through 10. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	07/31/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402457597	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214967
700900281	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214963