




<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: <u>09/12/2020</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead			# 1
Comment:			
Corrective Action:			Date:
Type: Plunger Lift			# 1
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:



**Inspected Facilities**

Facility ID: 286141 Type: WELL API Number: 123-24137 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: TANK BATTERY CONNECTED

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      **Weather Conditions: sunny, dry ground                      On Wednesday, August 12, 2020 at approximately 13:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at WAAG 25-22 (Bayswater Exploration &amp; Production LLC), at location #: 306185 in WELD COUNTY Colorado.                      While there, I observed a shut in wellhead.                      During this inspection the following possible compliance issues were observed:                      1. Appears to be stained soil at wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d. (Corrective Action Date: September 12, 2020) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	08/12/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603202	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222537">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5222537</a>