

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402374484

Date Received:

04/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Marie Florez

Phone

505-787-2218

Email

mflorez@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901547

Inspection Date: 03/16/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 333627

Location Name: COLORADO 32-7-N32N7W Number: 3SWNE County: LA PLATA

Qtrqr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049260 Longitude: -107.592280

FACILITY - API Number: 05-067- -00 Facility ID: 213910

Facility Name: COLORADO 32-7 Number: 11

Qtrqr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N

Latitude: 37.049260 Longitude: -107.592280

CORRECTIVE ACTIONS:

1 ☒ CA# 137329

Corrective Action: -Cleanup and properly dispose of impacted material by 3/25/2020.

Date: 03/25/2020

Response: CA COMPLETED

Date of Completion: 04/09/2020

Operator
Comment:

On 4/9/2020, LOGOS Operating LLC worked with the surface owner to cleanup and properly dispose of a concrete stain (impacted material), which is believed to have been caused by a contractor cleaning out their cement truck after working on the BIA ditch easement running through the property. Please note that the inspection was submitted to LOGOS on 3/20/2020, and, due to ongoing restrictions caused by COVID-19, LOGOS was unable to meet the required corrective action date of 3/25/2020.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 137330

Corrective Action: Remove and properly dispose of debris.

Date: 04/17/2020


Response: CA COMPLETED

Date of Completion: 04/09/2020

Operator Comment: In connection with the foregoing impacted material removal, on 4/9/2020, LOGOS has caused the weed debris around the wellhead and project facilities to be removed and properly disposed. The full rig anchor pattern has been subject to weed control. Because the approximately 100 Russian knapweeds from the western project area are outside of LOGOS's project area, we are not authorized to impact the surface owner's private property. We will, however, work with the surface owner to ensure awareness of the Russian knapweed and encourage weed control by the surface owner for the property outside of LOGOS's project area.

COGCC Decision: **Not Approved**

COGCC Representative: Operator comment does not demonstrate that corrective action is sufficiently addressed. COGCC has communicated with Logos on multiple occasions that the rig anchor pattern is not the extent of the project area, as the project area is defined as the extent of project disturbance. Followup inspection will be conducted to determine that weeds and debris are controlled within the project area.

3  CA# 137331

Corrective Action: Control weeds. Subsequent treatments will likely be needed.

Date: 06/01/2020

Response: CA COMPLETED

Date of Completion: 04/09/2020

Operator Comment: Consistent with LOGOS's standard operations, LOGOS will continue to spray weeds annually as a preventive measure and more frequently if required to control noxious weeds within our project areas.

COGCC Decision: **Not Approved**

COGCC Representative: Operator comment for debris, does not demonstrate that corrective action is sufficiently addressed for weeds. COGCC has communicated with Logos on multiple occasions that the rig anchor pattern is not the extent of the project area, as the project area is defined as the extent of project disturbance. Followup inspection will be conducted to determine that weeds and debris are controlled within the project area.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tamra Sessions

Signed:

Title: Regulatory Specialist

Date: 4/17/2020 3:02:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402374484	FIR RESOLUTION SUBMITTED
402374488	Concrete Stain
402374489	Concrete Stain
402374492	Wellhead

Total Attach: 4 Files