

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402394906

Date Received:
05/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Huntington, Heather</u>		<u>hhuntington@enduringresources.com</u>
<u>Walter, Kyle</u>		<u>kwalter@enduringresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901643
Inspection Date: 04/16/2020 FIR Submit Date: 04/16/2020 FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 326339

Location Name: WEST ANIMAS-UNIVERSITY-N34N9W Number: 9SWNW County: LA PLATA
Qtrqtr: SWN Sec: 9 Twp: 34N Range: 9W Meridian: N
W
Latitude: 37.220189 Longitude: -107.864608

FACILITY - API Number: 05-067-00 Facility ID: 216258

Facility Name: WEST ANIMAS-UNIVERSITY Number: 9-2
Qtrqtr: SWN Sec: 9 Twp: 34N Range: 9W Meridian: N
W
Latitude: 37.220189 Longitude: -107.864608

CORRECTIVE ACTIONS:

1 CA# 138104

Corrective Action: Remove and properly dispose of waste and debris. Revegetation will be needed in the area after the waste and debris is removed.

Date: 04/24/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

CORRECTIVE ACTIONS COMPLETED

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 138105

Corrective Action: Mark or remove rig anchors.

Date: 05/15/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator
Comment: CORRECTIVE ACTIONS COMPLETED

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 138107

Corrective Action: Stormwater controls need to be installed to stabilize erosion along the access road, and degradation due to deep rutting. Erosion and stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 01/31/2018

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator
Comment: CORRECTIVE ACTIONS COMPLETED

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: _____

Title: Permitting Technician

Date: 5/11/2020 1:29:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402394906	FIR RESOLUTION SUBMITTED
402394947	CA PHOTOS

Total Attach: 2 Files